



**Combo
Products**

BULLETIN NUMBER:

058

DATE: Mar. 78

RELATED
BULLETIN NO.

Service News

Issued by **YAMAHA Electronic Products Service Division**

CS-50,60,80

CHANGING CONSTANTS OF RESISTORS OF CONVERSION CONTROL IC (IG00151)

FOR IMPROVING ADJUSTMENT-WORK EFFICIENCY:

Changing the arrow-indicated constants from 100k Ω to 82k Ω .

CS-50

1. Main circuit board Changed parts: IC1~IC6 (6 parts) (Refer to Fig. 1)

2. Sub circuit board Changed parts: IC4~IC6, IC8 (4 parts) (Refer to Fig. 1)
CS-60

1. Main circuit board Changed parts: IC1~IC6 (6 parts) (Refer to Fig. 1)

2. Sub circuit board Changed parts: IC4~IC6, IC8 (4 parts) (Refer to Fig. 2)

CS-80

1. Main circuit board Changed parts: IC1~IC6 (6 parts) (Refer to Fig. 1)

2. Sub circuit board Changed parts: IC2, 4, 8, 10 (4 parts) (Refer to Fig. 1)

3. TRG1 circuit board Changed parts: IC1~IC24 (Refer to Fig. 3)

4. TRG2 circuit board Changed parts: IC1~IC24

5. TRG3 circuit board Changed parts: IC1~IC24

6. TRG4 circuit board Changed parts: IC1~IC16 (Refer to Fig. 3)

7. TRG5 circuit board Changed parts: IC1~IC17 (Refer to Fig. 3)

8. OE2 circuit board Changed parts: IC7~IC10 (4 parts) (Refer to Fig. 1)

OTHER CHANGES:

CS-50, 60 Preamplifier Circuit Board

CS-80 Preamplifier Circuit Board

EFFECTIVE PRODUCT DATE & SERIAL NO.:

March 1978 CS-50 No. 1976~

CS-60 No. 1620~

CS-80 No. 1304~